

Kolom1	Category	CIB nr	Serial #	Part of kit	Checked out for service or Status	Organization	Remarks User on Intake (Part of kit)	Remarks Rovin on Intake (Part of kit)
1	CT sensor	33469	N_0809_51 00164	735_1221 00012	14/09/2023	In Calibration	NKE HQ	periodiek
2	CT sensor	33477	N_0911_51 00201	735_1221 00022	14/09/2023	In Calibration	Rovin HQ	periodiek
3	CT sensor	33479	N_0906_51 00096	735_1221 00024	14/09/2023	In Calibration	Rovin HQ	Periodic maintenance
4	CT sensor	33480	N_1009_51 00171	735_1221 00025	14/09/2023	In Calibration	Rovin HQ	Periodic maintenance
5	CT sensor	33474	N_0809_51 00159	735_1221 00017	14/09/2023	Out for Service	NKE HQ	Error 80840412EB : Sensor not present. Sensor is properly fixed!
6	CT sensor	33475	N_0709_51 00151	735_1221 00020	14/09/2023	Out for Service	NKE HQ	Defect, sensor only gives half sensor message
7	CT sensor	33478	N_0809_51 00170	735_1221 00023	14/09/2023	Out for Service	NKE HQ	Defect, sensor gives data, but Sesam makes dummy values, new sensor works.
8	CT sensor	40908	N_0106_52 00090	735_0622 00004	14/09/2023	Out for Service	NKE HQ	UV Does not work
9	CT sensor	40893	N_0206_52 00119	735_0622 00019	14/09/2023	Out for Service	NKE HQ	big deviation , measures 15mS instead of 22mS/cm.happened on installation, new sensor!
10	CT sensor	40879	N_0206_52 00120	735_0622 00033	14/09/2023	Out for Service	NKE HQ	conductivity more then 10% of against reference
11	CT sensor	41129	N_0809_52 00145	735_1022 00018	14/09/2023	Out for Service	Rovin HQ	No connection
12	CT sensor	40882	N_0106_52 00099	735_0622 00030	17/10/2023	In Calibration	NKE HQ	guard is stuck
13	CT sensor	33485	N_0809_51 00153	735_1221 00030	17/10/2023	Out for Service	NKE HQ	No communication, code 0x04
14	CT sensor	33486	N_0209_51 00143	735_1221 00031	17/10/2023	Out for Service	NKE HQ	strange messages, water in UV LED
15	CT sensor	33490	N_1009_51 00187	735_1221 00035	17/10/2023	Out for Service	NKE HQ	water in UV LED
16	CT sensor	40898	N_0206_52 00126	735_0622 00014	17/10/2023	Out for Service	NKE HQ	fuse in RVS system fails
17	CT sensor	40886	N_0206_52 00118	735_0622 00026	17/10/2023	Out for Service	NKE HQ	UV LED not working.
18	CT sensor	41114	N_0609_52 00159	735_1022 00003	17/10/2023	Out for Service	NKE HQ	error
19	CT sensor	33464	N_0809_51 00154	735_1221 00007	17/10/2023	Out for Service	NKE HQ	sensor does not react, water behind LED